







STEP 1



STEP 2




STEP 3




POS 1

1 PC




POS 2

2 PCS



POS 3

1 PC



M4x8


POS 4

8 PCS




POS 5

2 PCS



POS 6

2 PCS



IVAR 2 / GW791-22

PAG. 2